

X(05)14 Asphalt Crack Repair on SR-191**PRODUCT/PROCESS**Category: **Asphalt Pavements**Trade Name: **Level & Go Repair Mastic**Manufacturer: **Deery American Corp.**Web Site: www.deeryamerican.comLocal Distributor: **Deery American Corp.**Web Site: www.deeryamerican.comUDOT R-52 No.: **03-078****STATUS**Work Plan (5%): [See Final Report](#)Construction Report (10%): [See Final Report](#)Interim Report (25% ea.): [See Final Report](#)Final Report (10%): [Complete](#)Total % Complete: **100%**

Notes:

LOCATIONReg./Dist.: **4/Price**Route: **SR-191**

Description:

Direction: **+/-**Beg. MP: **12.5**Description: **+/-**End MP: **20.4**

Description:

Structure No: **n/a****CONTACTS**Champion: **AJ Rogers**Research Primary: **Sharp**Email: rsharp@utah.govPhone: **(801)965-4314**Research Secondary: **Ken Berg**Email: kenberg@utah.govPhone: **(801)965-4321****GENERAL**Maintenance Station(s): **4421 Bluff**

Notes:

Project No.: **none**Job No: **8RD0780H**PIC: **XF05.014**